



STEP 1

In some cases, in order to meet ADA height, floors need to be separated over 2 panels because of return width.

This can be confusing for passengers.



STEP 2

TTG Touchscreen is a solution.

Touch buttons require less space than mechanical with tactiles. Result is more 'buttons' can be put in smaller space.

ADA/Accessibility is met via the keypad which is within required heights